START UP

1. Plug heat tool into standard wall outlet.

2. Turn the unit on. The noise will indicate that the motor driven fan is running. Heating coil will slowly light up dark red. There may be some smoking after the initial start up due to the burning out of manufacturing oils. Smoke will disappear in less than a minute.

   Nozzle will turn color with time because of high heat. This is normal and does not influence performance or life of the tool.

3. If motor is not running when switched on, turn off and unplug unit immediately. Return to dealer for replacement.

SHUTTING OFF

1. Move switch to "o" position and set the unit down with the nozzle pointing up and the stand in the support position.

2. Avoid holding the unit with the nozzle down after the shut-down either for storage or for a break in work since the residual heat would rise into the motor space and might shorten the life of the unit.

3. Store the unit only after the nozzle is cool to the touch.

4. It is a good idea to unplug the unit after use to prevent an accidental start-up by a fall or by children playing nearby.

EMBOSSING INSTRUCTIONS

1. Apply pigment ink pads or clear embossing ink pad to rubber stamp and stamp on paper, fabric, or wood. These inks are slow drying and will allow ample time to pour embossing powders on stamped images.

2. Use clear or translucent powders to allow the ink color to "rise and shine." Use opaque colors or metallic powders when you desire the embossing powder color to "rise and shine." Pour a generous amount of embossing powder onto stamped image. After entire image has been coated, return excess powder to jar.

3. Turn on heat tool and hold at a 45 degree angle. Keep tool a few inches from project. Point nozzle away from you and heat stamped image. As part of the image becomes raised and shiny, quickly move on to the rest of the image to avoid over-embossing.

To emboss hand-written messages, use embossing pen, embossing marker or glue pen. Embossing pens tend to work best with metallic embossing powders.

The heat tool is also the perfect heat source for puffing up Liquid Applique. After rubber stamping, apply Liquid Applique to desired areas. Heat immediately for bumpy effect. Allow to dry overnight before heating for "even puffing."

WARNING:
DO NOT IMMERSE IN WATER. FOR INDOOR USE ONLY.

Hidden areas such as behind walls, ceilings, floors, soffit boards and other panels may contain flammable materials that could be ignited by the heat tool when working in these locations. The ignition of these materials may not be readily apparent and could result in property damage and injury to persons.

When working in these locations, keep the heat tool moving in a back and forth motion. Lingering or pausing in one spot could ignite the panel or the material behind it.

IMPORTANT SAFETY INSTRUCTIONS

READ THESE INSTRUCTIONS

WARNING: Extreme care should be taken when stripping paint. The peelings residue and vapors of paint may contain lead, which is poisonous. Any pre-1977 paint may contain lead and paint applied to homes prior to 1950 is likely to contain lead. Once deposited on surfaces, hand to mouth contact can result in the ingestion of lead. Exposure to even low levels of lead can cause irreversible brain and nervous system damage: young and unborn children are particularly vulnerable.

Before beginning any paint removal process you should determine whether the paint you are removing contains lead. This can be done by you local health

department or by a professional who uses a paint analyzer to check the lead content of the paint to be removed. **LEAD-BASED PAINT SHOULD ONLY BE REMOVED BY A PROFESSIONAL AND SHOULD NOT BE REMOVED USING A HEAT TOOL.**

Persons removing paint should follow these guidelines:

1. Move the work piece outdoors. If this is not possible, keep the work area well ventilated. Open the windows and put an exhaust fan in one of them. Be sure the fan is moving the air from inside to outside.

2. Remove or cover any carpets, rugs, furniture, clothing, cooking utensils and air ducts.

3. Place drop cloths in the work area to catch any paint chips or peeling. Wear protective clothing such as extra work shirts, overalls and hats.

4. Work in one room at a time. Furnishings should be removed or placed in the center of the room and covered. Work areas should be sealed off from the rest of the dwelling by sealing doorways with drop cloths.

5. Children, pregnant or potentially pregnant women and nursing mothers should not be present in the work area until the work is done and all clean up is complete.

6. Wear a dust respirator mask or a dual filter (dust and fume) respirator mask which has been approved by the Occupational Safety and Health Administration (OSHA), the National Institute of Safety and Health (NIOSH), or the United States Bureau of Mines. These masks and replaceable filters are readily available at major hardware stores. Be sure the mask fits. Beards and facial hair may keep masks from sealing properly. Change filters often.

DISPOSABLE PAPER MASKS ARE NOT ADEQUATE.

7. Use caution when operating the heat tool. Keep the heat tool moving as excessive heat will generate fumes which can be inhaled by the operator.

8. Keep food and drink out of the work area. Wash hands, arms and face and rinse mouth before eating or drinking. Do not smoke or chew gum or tobacco in the work area.

9. Clean up all removed paint and dust by wet mopping the floors. Use a wet cloth to clean all walls, sills and any other surface where paint or dust is clinging. DO NOT SWEEP, DRY DUST OR VACUUM. Use a high phosphate detergent or trisodium phosphate (TSP) to wash and mop areas.

10. At the end of each work session put the paint chips and debris in a double plastic bag, close it with tape or twist ties, and dispose of it properly.

11. Remove protective clothing and work shoes in the work area to avoid carrying dust into the rest of the dwelling. Wash work clothes separately. Wipe shoes off with a wet rag that is then washed with the work clothes. Wash hair and body thoroughly with soap and water.

12. This appliance has a polarized plug (one blade is wider than the other). To reduce the risk of electric shock, this plug is intended to fit in a polarized outlet only one way. If the plug does not fit fully in the outlet, reverse the plug. If it still does not fit, contact a qualified electrician. Do not modify the plug in any way.

SAVE THESE INSTRUCTIONS

SAFETY

1. Do not leave turned-on heat tool unattended. Unplug tool before walking away for any length of time.

2. Do not allow use of heat tool by children.

3. To avoid burns and personal injury, do not touch the hot nozzle and never point the nozzle toward skin, hair, eyes and other parts of the body. This tool can not be used as a hair dryer. Avoid contact with artificial or acrylic finger nails.

4. Do not point the tool at surfaces which can be damaged by heat - plastic parts, painted, lacquered or varnished furniture.

5. Since moisture is electrically conductive, do not expose heat tool to water or moisture.

6. Do not use this tool in proximity of solvents and in closed spaces where solvent vapors can accumulate since they are explosive in mixture with air. Keep this tool away from dust, shredded paper and similar materials.

7. Do not block either the air intake or the nozzle since this would reduce the airflow and increase the temperature of the air as well as the internal parts of the tool. This may overload the tool and damage it.

8. Let the nozzle cool off until it can be touched before storing.

WARNING: Do not repair or disassemble this unit yourself. If under warranty, return with receipt to place of purchase for replacement. Opening of your heat tool while under warranty does void the warranty.

* DOUBLE INSULATED. WHEN SERVICING, USE ONLY IDENTICAL REPLACEMENT PARTS.